

Inverness North - Visual Façade Condition Survey Summary

Rating Scale:

3 = Poor Condition (Immediate Repair)
2 = Fair Condition (2-4 years)
1 = Acceptable Condition (4+ Years)

Quantities

Rating:	Front of Building	Side of Building	Rear of Building
3	10	10	24
2	21	15	48
1	27	13	52

Unit	Front	Rating	Side	Rating	Rear	Rating
7831	Cedar, T1-11	3	T1-11, Stucco	3	T1-11	1
7829	Stucco	-		-	T1-11	1
7827	Stucco, T1-11	3		-	T1-11	1
7825	Stucco	-		-	T1-11	1
7823	Stucco	-		-	T1-11	1
7821	Stucco	-	T1-11, Stucco	3	T1-11	1

Unit	Front	Rating	Side	Rating	Rear	Rating
7835	Stucco, T1-11	3	T1-11	3	T1-11	3
7837	Cedar, T1-11	1		-	T1-11	3
7839	Stucco	-		-	T1-11	3
7841	T1-11	2		-	T1-11	3
7843	Stucco, Cedar, T1-11	2		-	T1-11	3
7845	Cedar	-	T1-11	3	T1-11	3

Unit	Front	Rating	Side	Rating	Rear	Rating
7859	Stucco, Asphalt Shingles	-	Stucco, T1-11	3	T1-11	2
7861	Paster, Cedar	-		-	T1-11	3
7863	Stucco	-		-	T1-11	2
7865	Stucco, Cedar	-	Stucco, T1-11	3	T1-11	3

Unit	Front	Rating	Side	Rating	Rear	Rating
7849	Stucco, T1-11	1	Stucco, T1-11	1	T1-11	2
7851	Stucco	-		-	T1-11	2
7853	Stucco	-		-	T1-11	2
7855	Cedar	-	Cedar, Stucco, T1-11	1	T1-11	2

Unit	Front	Rating	Side	Rating	Rear	Rating
10701	Cedar, T1-11	2	Stucco, T1-11	2	T1-11	3
10703	Cedar, T1-11	3		-	T1-11	2
10705	Stucco	-		-	T1-11	1
10707	Cedar, Stucco, T1-11	3		-	T1-11	1
10709	Stucco, T1-11	2		-	T1-11	1
10711	Stucco	-	Stucco, T1-11	2	T1-11	1

Unit	Front	Rating	Side	Rating	Rear	Rating
10715	Paster, T1-11	2	Stucco, T1-11	2	T1-11	2
10717	Stucco	-		-	T1-11	2
10719	Cedar, T1-11	2	Stucco, T1-11	2	T1-11	2

Unit	Front	Rating	Side	Rating	Rear	Rating
10714	Stucco, Cedar	-	Stucco, T1-11	1	T1-11	2
10712	Stucco, Cedar	-		-	T1-11	2
10710	Stucco	-		-	T1-11	3
10708	Stucco, T1-11	1		-	T1-11	1
10706	Stucco, Cedar	-		-	T1-11	1
10704	Stucco, Asphalt Shingle	-		-	T1-11	1
10702	Stucco, Cedar, T1-11	1		-	T1-11	1
10700	Stucco, T1-11	1	Stucco, T1-11	1	T1-11	1

Unit	Front	Rating	Side	Rating	Rear	Rating
10676	Cedar, T1-11	2	Stucco, T1-11	1	T1-11	2
10674	Stucco	-		-	T1-11	2
10672	Plasster, T1-11	2		-	T1-11	2
10670	Plsater, Cedar	-		-	T1-11	1
10668	Stucco, Asphalt Shingle	-		-	T1-11	1
10666	Stucco	-		-	T1-11	2
10664	Stucco, Cedar, T1-11	2		-	T1-11	2
10662	Stucco, T1-11	2	Stucco, T1-11	2	T1-11	2

Unit	Front	Rating	Side	Rating	Rear	Rating
10644	Stucco	-	Stucco, T1-11	1	T1-11	1
10642	Stucco, Cedar, T1-11	1		-	T1-11	1
10640	Stucco, Asphalt Shingles	-		-	T1-11	3
10638	Stucco, T1-11	1		-	T1-11	2
10636	Stucco	-		-	T1-11	1
10634	Stucco, Asphalt Shingles	-	Stucco, T1-11	1	T1-11	1

Unit	Front	Rating	Side	Rating	Rear	Rating
10630	Stucco	-	Stucco, T1-11	1	T1-11	3
10628	Stucco, Cedar, T1-11	2		-	T1-11	1
10626	Stucco, Cedar	-		-	T1-11	3
10624	Stucco, Asphalt, T1-11	1		-	T1-11	1
10622	Stucco	-		-	T1-11	2
10620	Stucco, T1-11	2		-	T1-11	1
10618	Stucco, Asphalt Shingles	-	Stucco, T1-11	1	T1-11	2

Unit	Front	Rating	Side	Rating	Rear	Rating
10648	Stucco, Cedar	-	Stucco, T1-11	3	T1-11	1
10650	Stucco, T1-11	1		-	T1-11	1
10652	Stucco	-		-	T1-11	2
10654	Stucco, Cedar	-		-	T1-11	1
10656	Stucco, Cedar, T1-11	1		-	T1-11	1
10658	Stucco, T1-11 (URGENT)	3	Stucco, T1-11 (URGENT)	3	T1-11 (URGENT)	3

Unit	Front	Rating	Side	Rating	Rear	Rating
10614	Stucco, Cedar	-	Stucco, T1-11	3	T1-11	1
10612	Stucco, Cedar	-		-	T1-11	2
10610	Stucco, T1-11	2		-	T1-11	2
10608	Stucco	-		-	T1-11	2
10606	Stucco, Cedar, T1-11	1		-	T1-11	2
10604	Stucco	-		-	T1-11	2
10602	Stucco, T1-11	1		-	T1-11	1
10600	Cedar, T1-11	1	Stucco, T1-11	1	T1-11	2

Unit	Front	Rating	Side	Rating	Rear	Rating
10601	Stucco, T1-11	2	Stucco, T1-11	2	T1-11	1
10603	Stucco, T1-11	1		-	T1-11	1
10605	Paster, Cedar, T1-11	1		-	T1-11	1
10607	Stucco, Asphalt Shingles	-		-	T1-11	1
10609	Stucco	-		-	T1-11	1
10611	Stucco, Cedar, T1-11	2		-	T1-11	1
10613	Stucco	-		-	T1-11	1
10615	Cedar, T1-11	1	Stucco, T1-11	1	T1-11	1

Unit	Front	Rating	Side	Rating	Rear	Rating
10621	Stucco, Cedar	1	Stucco, T1-11	1	T1-11	1
10623	Stucco	-		-	T1-11	1
10625	Stucco, Cedar	-		-	T1-11	1
10627	Stucco, Cedar	-		-	T1-11	2
10629	Stucco, Cedar, T1-11	1		-	T1-11 (Urgent)	3
10631	Stucco	-		-	T1-11	2
10633	Stucco	-		-	T1-11 (Urgent)	3
10635	Stucco, Cedar	-	Stucco, T1-11	3	T1-11	1

Unit	Front	Rating	Side	Rating	Rear	Rating
10655	Stucco	-	Stucco, T1-11	2	T1-11	2
10657	Stucco, Cedar, T1-11	3		-	T1-11	3
10659	Stucco, Cedar	-		-	T1-11	2
10661	Stucco, Cedar, T1-11	2		-	T1-11	2
10663	Stucco	-		-	T1-11	3
10665	Stucco, T1-11	1		-	T1-11	1
10667	Stucco, Asphalt Shingle	-	Stucco, T1-11	2	T1-11	2

Unit	Front	Rating	Side	Rating	Rear	Rating
7848	Plater, T1-11	1	Stucco, T1-11	1	T1-11	1
7846	Stucco, Asphalt Shingle, T1-11	1		-	T1-11	1
7844	Stucco, Cedar	-		-	T1-11	3
7842	Stucco, Cedar, T1-11	1		-	T1-11	1
7840	Stucco	-		-	T1-11	1
7838	Stucco, T1-11	2		-	T1-11	2
7836	Stucco, Asphalt Shingle	-		-	T1-11	3
7834	Cedar, T1-11	2	Stucco, T1-11	2	T1-11	2

Unit	Front	Rating	Side	Rating	Rear	Rating
7830	Stucco	-	Stucco, T1-11	2	T1-11	2
7828	Stucco	-		-	T1-11	2
7826	Stucco, Cedar, T1-11	1		-	T1-11	3
7824	Stucco, Cedar	-		-	T1-11	3
7822	Stucco, T1-11	1		-	T1-11	2
7820	Stucco	-		-	T1-11	2
7818	Stucco, Cedar, T1-11	1		-	T1-11	2
7816	Stucco, T1-11	2	Stucco, T1-11	2	T1-11	2

Unit	Front	Rating	Side	Rating	Rear	Rating
7812	Stucco, Asphalt Shingle	-	Stucco, T1-11	2	T1-11	1
7810	Stucco, Cedar, T1-11	1		-	T1-11	1
7808	Stucco	-		-	T1-11	2
7806	Stucco, Cedar, T1-11	2		-	T1-11	2
7804	Stucco, Asphalt Shingle	-		-	T1-11	2
7802	Stucco, T1-11	2		-	T1-11	3
7800	Stucco	-	Stucco, T1-11	2	T1-11	1

Unit	Front	Rating	Side	Rating	Rear	Rating
7801	Cedar, T1-11	3	Stucco, T1-11	2	T1-11	1
7803	Stucco, Cedar, T1-11	1		-	T1-11	2
7805	Stucco	-		-	T1-11	1
7807	Stucco, Cedar, T1-11	3		-	T1-11	2
7809	Stucco, Cedar	-		-	T1-11	2
7811	Stucco, T1-11	3	Stucco, T1-11	2	T1-11	3